ERRATA SHEET FOR
ANSI/AMCA 204-05
Balance Quality and Vibration Levels for Fans
30 March 2006

The corrections in this errata sheet apply to ANSI/AMCA 204-05:

Page	Erratum
10	§§ 6.1.2, under the "EXAMPLE, LIMITS OF RELATIVE SHAFT VIBRATION": In each of the six equations that have two values in parenthesis, change the "H" to "×". The six 'as printed' and corrected equations are:

	As printed	Corrected
1.	Start-up/satisfactory = (0.25 H 0.33 mm)	Start-up/satisfactory = (0.25 × 0.33 mm)
2.	= (0.25 H 0.013 in.)	= (0.25 × 0.013 in.)
3.	Alarm = (0.50 H 0.33 mm)	Alarm = (0.50 × 0.33 mm)
4.	= (0.50 H 0.013 in.)	= (0.50 × 0.013 in.)
5.	Shut-down = (0.70 H 0.33 mm)	Shut-down = (0.70 × 0.33 mm)
6.	= (0.70 H 0.013 in.)	= (0.70 × 0.013 in.)

10	§§ 6.1.2, under "Combined mechanical and electrical run-out of the shaft at the point of vibration measurement:" : In two places, change the value "0.0052 mm" to "0.0206 mm".