



AMCA 301-06 Interpretation:

A request for clarification of the second paragraphs of both §5.3.1 and §5.4.1 was received by AMCA International' Technical Advisory Committee on Sound (TACOS). The following clarification was approved:

The fourth sentence in these two paragraphs (§5.3.1 and §5.4.1) should read, "If the blade pass frequency falls within ...of the two adjacent bands adjacent to that value using" Also, the addition of the following two figures would clarify the paragraphs.



Interpretation Figure 1 - When Blade Pass Frequency (BPF) value (X_{BPF}) falls outside of a 2% band limit



Interpretation Figure 2 - When Blade Pass Frequency (BPF) value (X_{BPF}) falls inside of a 2% band limit